# E-Zee Weblon No Show Fusible

## ~ A Medium Weight Backing Finisher with a Heat-Activated Adhesive

### E-Zee Weblon No Show Fusible 1.65

**oz**. is a low profile, soft and sheer Cut Away stabilizer with a heat-activated adhesive on one side. It is ideal as a backing finisher that is applied to the back side of finished embroidery to achieve a soft and smooth feel against the skin.

#### How to use Backing Finishers

- 1. The heat activated side of **E-Zee No Show Fusible 1.65 oz.** has shiny dots visible when looking at different angles.
- 2. After embroidering your design, turn the garment inside out to expose the back side.
- 3. Lay a piece of E-Zee No Show Fusible 1.65 oz. over the back side of the design with the rough side down.
- 4. Trace a trim line about ½" to ¾" larger than the finished embroidery. Be sure to round the corners and cut out.
- 5. Place the piece over the design evenly with the shiny dot side of E-Zee No Show Fusible 1.65 oz. facing down.
- 6. Fuse on by applying heat at 250° to 260° for approximately 10 to 20 seconds.

#### Please Note

Allow time for testing with the temperatures and time guidelines for best results.



800-225-3001 ezeebacking.com



Available in these sizes:

Pre-cuts - 100 pieces per pack • 8" x 8"

Rolls • 20" x 100 yards

Available in white and black



BACKING & TOPPING